

Graficzna prezentacja postępu robót

wykopy	maszp	stabilizacja	południowa	wiązła	w skierunku
DD14/C					
					0+160
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+900
					1+000
					1+100
					1+200
					1+300
					1+400
					1+500
					1+530,81

wykopy	maszp	stabilizacja	południowa	wiązła	w skierunku
DZ20/C					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+900
					1+000
					1+100
					1+200
					1+300
					1+400
					1+505,11

wykopy	maszp	stabilizacja	południowa	wiązła	w skierunku
DD21/C					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+900
					1+000
					1+100
					1+200
					1+300
					1+400
					1+500
					1+575,97

DD18/C					
					0+000
					0+100
					0+200
					0+300
					0+320,46

DD19/C					
					0+000
					0+100
					0+200
					0+290,38

DZ28/C					
					0+000
					0+100
					0+200
					0+300
					0+376,49

wykopy	maszp	stabilizacja	południowa	wiązła	w skierunku
DD16/C					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+900
					1+000
					1+100
					1+200
					1+300
					1+400
					1+500
					1+600
					1+700
					1+800
					1+900
					2+000
					2+100
					2+130,65

DD17/C					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+900
					1+000
					1+100
					1+200
					1+300
					1+400
					1+500
					1+600
					1+700
					1+800
					1+900
					2+000
					2+100
					2+200
					2+300
					2+321,75

DD15/C					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+510,41

DD22/C					
					0+002,88
					0+100
					0+200
					0+219,38

DD29/C					
					0+005
					0+100
					0+116,63

wykopy	maszp	stabilizacja	południowa	wiązła	w skierunku
DZ26/C					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+900
					1+000
					1+100
					1+200
					1+300
					1+400
					1+500
					1+600
					1+700
					1+800
					1+873,17

wykopy	maszp	stabilizacja	południowa	wiązła	w skierunku
DD23/C					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+900
					1+000
					1+100
					1+200
					1+300
					1+400
					1+500
					1+600
					1+700
					1+800
					1+900
					1+921,03

wykopy	maszp	stabilizacja	południowa	wiązła	w skierunku
DD25/C					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+900
					1+000
					1+100
					1+200
					1+300
					1+400
					1+500
					1+600
					1+700
					1+800
					1+833,77

DZ24/C					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+900
					1+000
					1+100
					1+200
					1+300
					1+400
					1+500
					1+600
					1+660,34

DD27/C					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+900
					1+000
					1+100
					1+200
					1+300
					1+393,38

DG 3					
					0+000
					0+100
					0+168,04

DG 4					
					0+000
					0+100
					0+200
					0+211,59

ŁĄCZNIK DD26/C i DD28/C					
					0+000
					0+099,92

DK7 RYCHNOWSKA WOLA					
					0+000
					0+100
					0+200
					0+300
					0+400
					0+500
					0+600
					0+700
					0+800
					0+847,14

ROBOTY WYKONANE DO OKRESU SPRAWOZDAWCZEGO					
ROBOTY WYKONANE W MIESIACU					
ROBOTY NIEPRZEWDZIANE DO WYKONANIA					
ROBOTY DO WYKONANIA					